

## ENGLISH

### Media converter series 9786/12-11

#### 1. General Information

- Read these operating instructions, especially the safety notes, carefully before use.
- Observe all other applicable documents (see also chapter 1.2)
- Keep the operating instructions throughout the service life of the device.
- Make the operating instructions accessible to operating and maintenance staff at all times.
- Pass the operating instructions on to each subsequent owner or user of the device.
- Update the operating instructions every time R. STAHL issues an amendment. The original instructions are the German edition. They are legally binding in all legal affairs.

#### 1.2 Further documents

- Data sheet
- Manual

For documents in other languages, see r-stahl.com.

#### 1.3 Conformity with standards and regulations

- IECEx, ATEX, EU Declaration of Conformity and further national certificates can be downloaded via the following link:  
<https://r-stahl.com/en/global/support/downloads/>
- IECEx is also available at: <https://www.iecex.com/>

#### 2. Intended use

The media converter series 9786 converts electrical RS485 signals into fibre optical signals and vice versa. Bus signals from PROFIBUS DP, Modbus RTU and R. STAHL Servicebus can be transmitted via the FO paths over distances of at least 2500 m. The inherently safe FO interfaces (Ex op is) mean that all of the media converter series 9786 can be interconnected and different FO network structures (line, ring topologies, etc.) can be established. The media converter 9786/12-11 has an RS485-IS interface and is suitable for use in Zone 1. "Intended use" includes complying with these operating instructions and the other applicable documents, e.g. the data sheets. All other uses are only intended after being approved by R. STAHL.

#### 3. Personnel qualification

Qualified specialist personnel is required to perform the activities described in these operating instructions.

**Specialists who perform these tasks must have a level of knowledge that meets applicable national standards and regulations.**

Additional knowledge is required for any activity in hazardous areas.

R. STAHL recommends having a level of knowledge equal to that described in the following standards:

- IEC/EN 60079-14 (Electrical installations design, selection and erection)
- IEC/EN 60079-17 (Inspection and maintenance of electrical installations)
- IEC/EN 60079-19 (Equipment repair, overhaul and reclamation)

#### 4. Safety

##### 4.1 Explosion hazard

Despite the device's state-of-the-art design, explosion hazards cannot be entirely eliminated in hazardous areas.

- Perform all work steps in hazardous areas with the utmost care at all times!
- Transport, store, plan, mount and operate the device exclusively in compliance with the technical data (see the "Technical data" chapter).

##### 4.2 Mechanical damage

The device may be damaged during transport, mounting or commissioning. This kind of damage may, for example, render the device's explosion protection partially or completely ineffective. This may result in explosions causing serious or even fatal injury.

- Only transport the device in special transport packaging that reliably protects the device from external influences. Take ambient conditions into account when selecting the transport packaging (see the "Technical data" chapter).
- Do not place any loads on the device.
- Check the packaging and the device for damage. Report any damage to R. STAHL immediately. Do not commission a damaged device.
- Store the device in its original packaging in a dry place (with no condensation) and make sure that it is stable and protected against the effects of vibrations and knocks.
- Do not damage the device and other system components during mounting.

##### 4.3 Excessive heating or electrostatic charge

An incorrect setup in the cabinet, operation outside of approved conditions or improper cleaning can cause the device to heat up severely or to become electrostatically charged, causing it to produce sparks.

This may result in explosions causing serious or even fatal injury.

- Operate the device within the prescribed operating conditions only (see the label on the device and the "Technical data" chapter).
- Install and set up the cabinet in such a way that all devices installed within it are always operated within their permissible temperature range.
- Connect the enclosure of the device to the equipotential bonding.

##### 4.4 Ignition sparks

Ignition sparks can be generated during live working, when working with screws or routing connections on a device that has not been fitted according to regulations. This may result in explosions causing serious or even fatal injury.

- Carry out all screw fastening processes carefully using the respectively specified tightening torques.
- Sufficiently secure all communication lines against tensile force (e.g. by tightening the strain relief cap, cable ties, screws).
- During operation: De-energise all connected modules and devices before connecting or disconnecting auxiliary power supply connections.

## ENGLISH

### 4.5 Improper project engineering, mounting, installation, commissioning, maintenance or cleaning

Basic work such as installation, commissioning, maintenance or cleaning of the device must be performed only in accordance with the applicable national regulations of the country of use and only by qualified persons. Otherwise, the explosion protection may be rendered ineffective. This may result in explosions causing serious or even fatal injury.

- When used in Zone 1 or Zone 2, the device is to be installed in a protective enclosure or in a cabinet that offers a suitable degree of protection in accordance with IEC/EN 60079-0.
- When used in Zone 21 or Zone 22, the device is to be installed in a protective enclosure or in a cabinet that offers a suitable degree of protection in accordance with IEC/EN 60079-31.
- Only operate the device with a correctly positioned IP30 cover above the connection terminals (screw heads of the terminal are not visible from above).
- Repair work on the device must be performed only by R. STAHL.
- Gently clean the device with a damp cloth only – do not use scratching, abrasive or aggressive cleaning agents or solutions.
- Only use the device with original accessories from R. STAHL Schaltgeräte.

#### 5. Device design (1)

#	Device element	Description
1	Case ground	Connection of the enclosure to the equipotential bonding
2	LED displays	"PWR": Auxiliary power display "RS485-IS": RS485-IS interface status display "Port A": FO port A status display "Port B": FO port B status display
3	Terminal error signal output	Signalling of error conditions
4	Shield earthing	Connection of the RS485 line shield to the equipotential bonding
5	FO ports	Fibre optic connection
6	Auxiliary power terminal	Auxiliary power connection
7	IP30 cover	Protection for auxiliary power connection
8	Rotary switch	Selection of baud rate and operating mode
9	Sub-D socket	RS485-IS interface
10	Screw	Selection of shield earthing – capacitive or direct (hard)

#### 6. Product selection and project engineering

See manual

#### 7. Mounting and installation

##### DANGER! Explosion hazard from combustible sparks when used in Zone 1 and Zone 2.

Non-compliance results in severe or fatal injuries.

- Only install and connect the device in a de-energised state.
- Install the device in an enclosure with an IP degree of protection of at least IP54 according to EN IEC 60079-0.
- If necessary, use heat dissipation measures to ensure that the device's permissible service temperature is not exceeded in this enclosure, even in unfavourable ambient conditions.
- If there is a cross-functional connection via the fibre optic: Only use additional lens systems or light amplifiers if they are explicitly approved for this use.

##### 7.1 Mounting (1)

- Mount the device on a DIN rail (TH35 according to EN 60715).
- Maintain a distance at the side of  $\geq 5$  mm from other devices.

##### 7.2 Installation

##### Connecting the auxiliary power

In order to connect the auxiliary power, the device has a two-pole Ex e terminal.

##### DANGER! Explosion hazard from combustible sparks when used in Zone 1 or 2.

Non-compliance results in severe or fatal injuries.

- Only connect the device if it is de-energised or in a safe area (no explosive atmosphere).

The connection cross-section is as follows:

	Single-wire connection	Dual-wire connection
Rigid	0.2 to 2.5 mm <sup>2</sup>	0.2 to 0.75 mm <sup>2</sup>
Flexible with core end sleeve	0.2 to 1.5 mm <sup>2</sup>	0.2 to 0.34 mm <sup>2</sup>

- Strip the connecting lines (9 mm).
- For stranded wires: Use core end sleeves.
- Slightly loosen the mounting screws of the IP30 cover.
- Move the cover until the screw heads of the terminal are visible from above.
- Connect the supply voltage to the + and - terminals.
- Tighten the terminals (tightening torque: 0.4 to 0.5 Nm).
- Move the IP30 cover until the cover is flush with the enclosure.
- Secure the mounting screws.

##### Connecting the equipotential bonding

- Connect the M5 x 1 bolt ("Case Ground") on the device to the equipotential bonding.

##### Connecting the RS485 shield

Depending on the expected interference and the installation, users can choose between capacitive and direct (hard) earthing. The shield is capacitively connected ex works to the connection for the shield earthing (1), device element #4).

For this purpose, an insulating disc is inserted between the screw head and the line shield.

- If you choose direct earthing: Unscrew the screw, remove the insulating disc and retighten the screw.
- If the connection for the shield earthing is to be connected to the "Case Ground" enclosure potential: Connect the M5 x 1 bolt to the M5 x 1 bolt ("Case Ground").

##### Connecting the media converter to fieldbus

The fieldbus interface is a 9-pole Sub-D socket.

- Connect the device to the fieldbus using a Sub-D plug connector approved for Ex applications (e.g. item no. 162693 (straight) or 201805 (angled)).
- Tighten the mounting screws of the Sub-D connector.

## DEUTSCH

### Medienkonverter Reihe 9786/12-11

#### 1. Allgemeine Angaben

##### 1.1 Zu dieser Betriebsanleitung

- Diese Betriebsanleitung, insbesondere die Sicherheitshinweise, vor Gebrauch aufmerksam lesen.
  - Alle mitgelieferten Dokumente beachten (siehe auch Kapitel 1.2)
  - Betriebsanleitung während der Lebensdauer des Geräts aufzubewahren.
  - Betriebsanleitung dem Bedien- und Wartungspersonal jederzeit zugänglich machen.
  - Betriebsanleitung an jeden folgenden Besitzer oder Benutzer des Geräts weitergeben.
  - Betriebsanleitung bei jeder von R. STAHL erhaltenen Ergänzung aktualisieren.
- Die Originalbetriebsanleitung ist die deutsche Ausgabe.  
Diese ist rechtsverbindlich in allen juristischen Angelegenheiten.

##### 1.2 Weitere Dokumente

- Datenblatt
- Handbuch

Dokumente in weiteren Sprachen, siehe r-stahl.com.

##### 1.3 Konformität zu Normen und Bestimmungen

- IECEx, ATEX, EU-Konformitätsurkunde und weitere nationale Zertifikate stehen unter folgendem Link zum Download bereit:  
<https://r-stahl.com/de/global/support/downloads/>
- IECEx zusätzlich unter: <https://www.iecex.com/>

#### 2. Bestimmungsgemäße Verwendung

Der Medienkonverter der Reihe 9786 konvertiert elektrische RS485-Signale in optische Signale und umgekehrt. Über die LWL-Strecken können die Bussignale von PROFIBUS DP, Modbus RTU und R. STAHL Service Bus über Entfernen von mindestens 2500 m übertragen werden. Über die inhärent sicheren LWL-Schnittstellen (Ex op is) können alle Medienkonverter der Reihe 9786 zusammen geschaltet und verschiedene LWL-Netzwerkstrukturen (Linie, Ringtopologien ...) aufgebaut werden. Der Medienkonverter 9786/12-11 verfügt über eine RS485-IS-Schnittstelle und eignet sich zum Einsatz in Zone 1. Zur bestimmungsgemäßen Verwendung gehört die Beachtung dieser Betriebsanleitung und der mitgelieferten Dokumente, z.B. der Datenblätter. Alle anderen Anwendungen sind nur nach Freigabe der Firma R. STAHL bestimmungsgemäß.

#### 3. Qualifikation des Personals

Für die in dieser Betriebsanleitung beschriebenen Tätigkeiten ist eine entsprechend qualifizierte Fachkraft erforderlich.

**Fachkräfte, die diese Tätigkeiten ausführen, müssen einen Kenntnisstand haben, der relevante nationale Normen und Bestimmungen umfasst.**

##### Für Tätigkeiten in explosionsgefährdeten Bereichen sind weitere Kenntnisse erforderlich!

R. STAHL empfiehlt einen Kenntnisstand, der in folgenden Normen beschrieben wird:

IEC/EN 60079-14 (Projektierung, Auswahl und Errichtung elektrischer Anlagen)

IEC/EN 60079-17 (Prüfung und Instandhaltung elektrischer Anlagen)

IEC/EN 60079-19 (Gerätereparatur, Überholung und Regenerierung)

#### 4. Sicherheit

##### 4.1 Explosionsgefahr

Im explosionsgefährdeten Bereich kann, trotz Konstruktion des Geräts nach aktuellem Stand der Technik, eine Explosionsgefahr nicht gänzlich ausgeschlossen werden.

- Alle Arbeitsschritte in explosionsgefährdeten Bereichen stets mit größter Sorgfalt durchführen!
- Gerät nur unter Einhaltung der Technischen Daten (siehe Kapitel "Technische Daten") transportieren, lagern, projektiert, montieren und betreiben.

##### 4.2 Mechanische Beschädigung

Während des Transports, der Montage oder der Inbetriebnahme kann das Gerät beschädigt werden.

Solche Beschädigungen können unter anderem den Explosionschutz des Geräts teilweise oder komplett aufheben. Explosonen mit tödlichen oder schweren Verletzungen von Personen können die Folge sein.

- Gerät ausschließlich in besonderer Transportverpackung befördern, die das Gerät vor äußeren Einflüssen sicher schützt. Bei der Auswahl der Transportverpackung Umgebungsbedingungen (siehe Kapitel "Technische Daten") berücksichtigen.
- Gerät nicht beladen.

Verpackung und Gerät auf Beschädigung prüfen. Beschädigungen umgehend an R. STAHL melden. Beschädigtes Gerät nicht in Betrieb nehmen.

- Gerät in Originalverpackung, trocken (keine Betauung), in stabiler Lage und sicher vor Erschütterungen lagern.
- Gerät und weitere Systemkomponenten während der Montage nicht beschädigen.

**4.3 Übermäßige Erwärmung oder elektrostatische Aufladung**

Durch eine fehlerhafte Einrichtung im Schaltschrank, durch den Betrieb außerhalb zugelassener Bedingungen oder eine unsachgemäße Reinigung kann sich das Gerät stark erwärmen, elektrostatisch aufladen und somit Funken auslösen. Explosonen mit tödlichen oder schweren Verletzungen von Personen können die Folge sein.

- Gerät nur innerhalb der vorgeschriebenen Betriebsbedingungen betreiben (siehe Kennzeichnung auf dem Gerät und Kapitel "Technische Daten").
- Schaltschrank so aufzubauen und einzurichten, dass alle darin installierten Geräte immer innerhalb ihres zulässigen Temperaturbereichs betrieben werden.
- Gehäuse des Geräts mit dem Potentialausgleich verbinden.

## ENGLISH

### Connecting fibre optics

**WARNING!** Risk of injury to eyes from laser beams from devices according laser class 1.

Non-compliance can result in severe or fatal injuries.

- During operation do not look directly into the emitting diodes or into the optical fibre while using optical aids.
- Insert the the ST connector of the fibre optics into the ST socket of the transmit and receive channel.
- Press the spring mechanism of the ST connector downwards.
- Turn the ST connector a quarter rotation to the right until the connector is securely locked.

### Connecting the error signal output

The 9786/12-11 device has a NAMUR error signal output.

The error signal output can be connected to a NAMUR input module according to IEC/EN 60947-5-6 (e.g. IS1+ 9468, 9470).

The connection cross-section (terminal: Error signal output) is as follows:

	Single-wire connection	Dual-wire connection with the same cross section with TWIN core end sleeve
Rigid	0.2 to 2.5 mm <sup>2</sup>	—
Flexible with core end sleeve	0.25 to 2.5 mm <sup>2</sup>	0.5 to 1.5 mm <sup>2</sup>

- Connect the error signal output using the two-pole push-in connector.
- Remove the push-in plug connector from the packaging and insert it into the connection strip.
- Secure the plug connector using the screw locking (tightening torque: 0.3 Nm).
- Strip the connecting lines (10 mm).
- For flexible cores: Use core end sleeves.
- Insert the core into the terminal to as far as the insulation.

### Connecting to end-of-line resistors

- Connect to end-of-line resistors at the beginning and the end of each segment.

## ENGLISH

### 8. Parameterisation and commissioning

For PROFIBUS-DP, the transfer rate is automatically detected by the device. For other, byte-oriented, serial data streams, the transfer rate must be set permanently using a rotary switch (position 3 to 9).

Rotary switch position	Transfer rate/topology
0	PROFIBUS-DP: Automatic baud rate detection   Point-to-point connection
1	PROFIBUS-DP: Automatic baud rate detection   Ring master
2	PROFIBUS-DP: Automatic baud rate detection   Ring device
3	Modbus RTU: 9.6 kbps, even parity
4	Modbus RTU: 19.2 kbps, even parity
5	Modbus RTU: 38.4 kbps, even parity
6	Modbus RTU: 57.6 kbps, even parity
7	Modbus RTU: 9.6 kbps, uneven parity, (for IS1+ Servicebus)
8	Modbus RTU: 38.4 kbps, uneven parity, (for IS1+ Servicebus)
9	PROFIBUS-DP: Automatic baud rate detection   Without fault message for port B   Point-to-point connection

Before commissioning, carry out the following checks:

- Check the device and lines for damage.
- Mounting and installation of the device according to regulations.
- Correct, secure connection of the lines.
- The screws are securely fastened to the terminal.
- Correct position of the IP30 cover.

### 9. Operation

After connecting the lines and activating the supply voltage, the device will automatically go into operation.

#### 9.1 Displays

LED	Colour	Meaning
"PWR"	off	No supply voltage/supply voltage too low
LED	green	Supply voltage error-free
red		Fault/malfunction inside the device
"RS485-IS"	off	No bus communication
LED	yellow	Bus communication active
	blinking yellow	Baud rate determination active
	red	Communication error
"Port A"	off	No bus communication
LED	yellow	Bus communication active
	blinking red	Telegrams partially defective
	red	Communication error
"Port B"	off	No bus communication
LED	yellow	Bus communication active
	blinking red	Telegrams partially defective
	red	Communication error

### 10. Repair

- Repair work on the device must be performed only by R. STAHL.

### 11. Disposal

- Observe national, local and statutory regulations regarding disposal.
- Separate materials for recycling.
- Ensure environmentally friendly disposal of all components according to statutory regulations.

## DEUTSCH

### Lichtwellenleiter anschließen

**WARNING!** Augenverletzung durch Laserstrahlen bei Geräten der Laserklasse 1!

Nichtbeachten kann zu schweren oder tödlichen Verletzungen führen.

- Während des Betriebs niemals direkt in die Sendedioden oder mit optischen Hilfsmitteln in die Glasfaser blicken.
- ST-Stecker der Lichtwellenleiter auf ST-Buchse des Sende- und Empfangskanals stecken.
- Federmechanismus des ST-Steckers nach unten drücken.
- ST-Stecker um eine Vierteldrehung nach rechts drehen, bis der Stecker fest arretiert ist.

### Fehlermeldeausgang anschließen

Das Gerät 9786/12-11 verfügt über einen NAMUR-Fehlermeldeausgang. Der Fehlermeldeausgang kann an ein NAMUR-Eingangsmodul gemäß IEC/EN 60947-5-6 (z.B. IS1+ 9468, 9470) angeschlossen werden.

Der Anschlussquerschnitt (Klemme: Fehlermeldeausgang) beträgt:

	einadriger Anschluss	zweadriger Anschluss mit gleichem Querschnitt mit TWIN-Aderendhülse
starr	0.2 ... 2.5 mm <sup>2</sup>	—
flexibel mit Aderendhülse	0.25 ... 2.5 mm <sup>2</sup>	0.5 ... 1.5 mm <sup>2</sup>

Vor Inbetriebnahme folgende Prüfschritte durchführen:

- Fehlermeldeausgang über den 2-poligen Push-In-Stecker anschließen.
- Push-In-Steckverbinder aus der Verpackung entnehmen und in die Stifteleiste stecken.
- Steckverbinder mit Hilfe der Schraubverriegelung sichern (Anzugsdrehmoment: 0.3 Nm).
- Verbindungsleitungen abisolieren (10 mm).
- Bei flexiblen Adern: Aderendhülsen verwenden.
- Ader bis zur Isolierung in die Klemme stecken.

### Abschlusswiderstände zuschalten

- Am Anfang und Ende jedes Segments Abschlusswiderstände zuschalten.

## DEUTSCH

### 8. Parametrierung und Inbetriebnahme

Die Übertragungsrate wird bei PROFIBUS-DP automatisch vom Gerät erkannt. Für andere byteorientierte, serielle Datenströme muss die Übertragungsrate über einen Drehschalter (Position 3 ... 9) fest eingestellt werden.

Position Drehschalter	Übertragungsrate/Topologie
0	PROFIBUS-DP: automatische Baudratenerkennung   Punkt-zu-Punkt-Verbindung
1	PROFIBUS-DP: automatische Baudratenerkennung   Ring-Master
2	PROFIBUS-DP: automatische Baudratenerkennung   Ring-Device
3	Modbus RTU: 9.6 kbps, gerade Parität
4	Modbus RTU: 19.2 kbps, gerade Parität
5	Modbus RTU: 38.4 kbps, gerade Parität
6	Modbus RTU: 57.6 kbps, gerade Parität
7	Modbus RTU: 9.6 kbps, ungerade Parität, (für IS1+ Service Bus)
8	Modbus RTU: 38.4 kbps, ungerade Parität, (für IS1+ Service Bus)
9	PROFIBUS-DP: automatische Baudratenerkennung   ohne Störmeldung für Port B   Punkt-zu-Punkt-Verbindung

Vor Inbetriebnahme folgende Prüfschritte durchführen:

- Gerät und Leitungen auf Schäden prüfen.
- Vorschriftsmäßige Montage und Installation des Gerätes.
- Korrekt, fester Anschluss der Leitungen.
- Fester Sitz der Schrauben an der Klemme.
- Korrekte Position der IP30-Abdeckung.

### 9. Betrieb

Nach Anschluss der Leitungen und Aufschalten der Versorgungsspannung geht das Gerät automatisch in Betrieb.

#### 9.1 Anzeigen

LED	Farbe	Bedeutung
LED "PWR"	aus	Versorgungsspannung zu niedrig/fehlert
	grün	Versorgungsspannung fehlerfrei
	rot	geräteinterne Störung/Fehlfunktion
LED "RS485-IS"	aus	keine Buskommunikation
	gelb	Buskommunikation aktiv
	blinkt gelb	Baudratenermittlung aktiv
	rot	Kommunikationsfehler
LED "Port A"	aus	keine Buskommunikation
	gelb	Buskommunikation aktiv
	blinkt rot	Telegramme z.T. fehlerhaft
	rot	Kommunikationsfehler
LED "Port B"	aus	keine Buskommunikation
	gelb	Buskommunikation aktiv
	blinkt rot	Telegramme z.T. fehlerhaft
	rot	Kommunikationsfehler

### 10. Reparatur

- Reparaturen am Gerät nur durch R. STAHL durchführen lassen.

### 11. Entsorgung

- Nationale und lokal gültige Vorschriften und gesetzliche Bestimmungen zur Entsorgung beachten.
- Materialien getrennt dem Recycling zuführen.
- Umweltgerechte Entsorgung aller Bauteile gemäß den gesetzlichen Bestimmungen sicherstellen.

## DEUTSCH

### Technische Daten

#### Explosionsschutz

Global (IECEx)

Gas  
Dust

Europe (ATEX)

Gas  
Dust

Certificates

RS485-IS

Max. voltage U<sub>0</sub>

Max. current I<sub>0</sub>

Max. power P<sub>0</sub>

Max. connectable voltage U<sub>i</sub>

Internal capacitance C<sub>i</sub>

Internal inductance L<sub>i</sub>

Error signal output

Max. connectable voltage U<sub>i</sub>

Internal capacitance C<sub>i</sub>

Internal inductance L<sub>i</sub>

EPL FO interfaces

Safety-related maximum voltage U<sub>m</sub>

Electrical data

Nominal voltage

Voltage range

Current consumption

Power consumption

Auxiliary power connection

RS485-IS signal level

RS485-IS connection

FO connection

FO type

Error signal output

Error signal output connection

Electromagnetic compatibility

Galvanic separation

Ambient conditions

Ambient temperature

